

RETURN

2007

Inspector bg

Date 19.04.07

Site Meols Rec Ground

Inspectors Comments The playground is located adjacent to football area and located at cross roads. Old equipment, severe rust in parts of Multi Unit. Plan replacement 1 year.

The following have been inspected and are in satisfactory condition. Where standard failures are of a minor nature, or there is no practical economic remedial action and associated risks are acceptable, no action has been recommended. EN1176 and EN1177 are not mandatory or retrospective. See Notes



Site		Equipment		
Ancillary Items	Item	Manufacturer	EN	Surface
Access Fencing Seats x 4 Litter Bins x 2 Minimum Space Movement Clash Cleanlines				