

**Work is recommended on the following items
Site and other Hazards**

Item	Recommended	EN	Surface	ENS	Action Required	Priority
Road Signs	Firm surface pathway recommended			Y	Plan replacement of this item	3
Pathways	Adjust self closer		Woodchip		Ensure firm grips and even spacings. The protective surface under all bars must be kept in good condition	4
Gates x 2	Dog Ban & Ownership Signs recommended (See www.rospa.com/playsafety/info/18_signs.pdf)				Paintwork in poor condition - De-scale and coat with lead free paint, using appropriate precautions	2
Signs	Repair damage				Metal fatigue, barrier rusted through - Replace	3
Vehicle Access					Rake and fork over and top up as required to maintain minimum depth (usually 300mm)	3
					Shrinkage separation - Seal gaps before worsening	
					Trip zones at edge of impact attenuating surface - Build up ground levels to remove trip hazard	
					Paintwork in poor condition - De-scale and coat with lead free paint, using appropriate precautions	
					Round off and smooth edges of head section (missing ears)	
					Remove shackle bolt and check bush and shackle pin wear, replacing if necessary	
					Remove shackle bolt and check bush and shackle pin wear, replacing if necessary	
					Paintwork in poor condition - De-scale and coat with lead free paint, using appropriate precautions	
					Shrinkage separation - Seal gaps before worsening	
					Trip zones at edge of impact attenuating surface - Build up ground levels to remove trip hazard	

TOP

Meols Rec Ground